

Clock In Time:		Clock Out Time:	
Lunch Start Time:		Lunch Finish Time:	

# List of Activities

10:05 PM, Fri, Jul 18  
541 Cythia Brook, Hongshire, CA, 88452 | (demo) Geoffrey Corkery | 100.673.9990 x3962  
Lawn and Garden Sprinkler System - Repair  
Type: Job, Status: Completed  
Assigned To: Alonzo Shanahan  
Product & Services: ["Lawn and Garden Sprinkler System - Repair"]  
Lawn size: 330

Start Time: \_\_\_\_\_ End Time: \_\_\_\_\_

11:34 PM, Fri, Jul 18  
Maintenance Task: Brinly Tow-Behind Sleeve Hitch Box Scraper  
Type: Task, Status: Completed  
Assigned To: Gerardo Hermann  
Equipment: Brinly Tow-Behind Sleeve Hitch Box Scraper

Start Time: \_\_\_\_\_ End Time: \_\_\_\_\_