

Clock In Time:		Clock Out Time:	
Lunch Start Time:		Lunch Finish Time:	

List of Activities

07:46 AM, Sun, Sep 07
Maintenance Task: Brinly Tow-Behind Spike Aerator
Type: Task, Status: Completed
Assigned To: Brent Welch
Equipment: Brinly Tow-Behind Spike Aerator

Start Time: _____ End Time: _____

11:28 AM, Sun, Sep 07
7750 Emogene Creek, Daliafort, CA, 48007 | Lemke, Padberg and Kunze ((demo) Shonta Pacocha) | 234.954.1465 x7596
Outdoor Lighting - Repair/Install
Type: Job, Status: Completed
Assigned To: Jayna Cummerata
Product & Services: ["Gazebo or Freestanding Porch - Repair", "Outdoor Lighting - Repair/Install"]

Start Time: _____ End Time: _____